

PW MILLAR LTD

ESTABLISHED 1970

2019-19 | LAND ROVER RANGE

ROVER SPORT

2.0 P400e 13.1kWh HSE Dynamic Auto 4WD Euro 6
(s/s) 5dr | Hybrid | Automatic | Loire Blue



<https://www.pwmillarford.co.uk>
01446 733248



£20,999

Mileage	68,898 miles
Fuel	Hybrid
Owners	1
Engine	2 litre
Transmission	Automatic
Gears	8
Insurance group	50E

SPECIFICATIONS

Red brake calipers	Navigation pro system with 10" touch screen, app interface and media storage	HSE badge
Roller blind loadspace cover	Smartphone pack - Range Rover Sport	Terrain Response 2 with dynamic program
Dark engine turned aluminium trim finisher	Intrusion sensor	DAB Radio (Digital Audio Broadcasting)
21" 5 split spoke gloss sparkle silver finish alloy wheels - style 5085	DSC - Dynamic Stability Control	Push button start
Twin bright tailpipes	3 seat bench in 2nd row	Smoker's pack - Range Rover Sport
Public charging cable	Remote locking	USB/aux input socket
Tyre repair system	Height adjustable front seatbelts	All Terrain Info Centre
P400e badge	Isofix child seat preparation	Non smoker's pack - Range Rover Sport
Adaptive dynamics	Locking wheel nuts	No CD/DVD player
EBD - Electronic brakeforce distribution	Rear view camera	Electrical towing preparation
Rear centre armrest	Twin speed transfer box	Keyless entry
Bluetooth audio streaming	Hill descent control	Electric power assisted steering (EPAS)
Adaptive brake lights	Three 12V accessory power outlets	7 kW onboard charger
Secure tracker	CD/DVD player	Low traction launch

TECHNICAL

Performance	
0-100 kmh (62 mph)	6.3 s
Top speed	137 mph
Emissions Ice	
CO ₂ (g/km)	69 (g/km)
Fuel Consumption Ice	
MPG (combined)	94.2 mpg
Electric Vehicle Data	
Charging timings	
0-100% in 450 min at 2.3 kW	
0-100% in 165 min at 7 kW	
Battery type	Lithium-ion
Total capacity	13.1 kWh
Capacities	
Boot (seats up)	703 litres
Boot (seats down)	1607 litres
Fuel tank	90 litres

....MORE.... For the full details please call us or scan the QR code above

01446 733248

sales@pwmillar.co.uk

P W Millar 148 Port Road East Barry South Glamorgan CF62 9PZ

Whilst every effort has been made to ensure the accuracy of the vehicle specification, some inaccuracies may occasionally occur. It is important that you do not rely solely on this information, but check with a member of the sales staff about any features which may affect your decision to buy the car.