

PW MILLAR LTD

ESTABLISHED 1970

2016-16 | **BMW 2 SERIES**

1.5 218i M Sport Euro 6 (s/s) 2dr Cabriolet | Petrol | Manual | Glacier Silver



<https://www.pwmillarford.co.uk>
01446 733248



£9,399

From **£240** per month HP

Mileage	48,275 miles
Fuel	Petrol
Owners	1
Engine	1.5 litre
Transmission	Manual
Gears	6
Insurance group	22E

SPECIFICATIONS

Driver seatbelt warning indicator	Check control system	Daytime running lights
Luggage compartment lighting	M sport suspension	Aluminium hexagon interior trim with estoril blue finish
Remote central locking	DAB Digital radio	18" light alloy wheels - M Double spoke style 461M
Driver/Front Passenger airbags	Outside temperature display	Body colour door mirrors
Sunvisors with vanity mirrors	Drive Performance Control	Electronic immobiliser
BMW professional radio/CD/MP3	Run flat tyres	Hill start assist
Oil temperature gauge	2 speed adjustable intermittent wipers with wash/wipe function	Glovebox with lid
Remote control Thatcham category 1 alarm	6 speakers	DSC+
Bluetooth hands free telephone connection with USB audio interface + audio streaming	Dual chrome exhaust	Reach + rake adjustable steering column
Drive away door locking	Auxiliary point for auxiliary devices	Crash Sensor - activates hazard/interior lighting + unlocks doors
On board computer	Body colour bumpers	Front door storage bins
Front seatbelt pretensioner	Service interval indicator	Electric front and rear windows with fingertip open/close + anti-trap all round
Lashing eyelets in boot	Cornering brake control (CBC)	BMW Teleservices
High gloss shadow line	4 grab handles	Front seatbelt force limiters

TECHNICAL

Performance	
0-100 kmh (62 mph)	9.4 s
Top speed	128 mph
Emissions Ice	
CO ₂ (g/km)	139 (g/km)
Fuel Consumption Ice	
MPG (combined)	47.1 mpg
MPG (extra urban)	55.4 mpg
MPG (urban)	37.7 mpg
Capacities	
Boot (seats up)	335 litres
Fuel tank	52 litres

....MORE.... For the full details please call us or scan the QR code above

01446 733248

sales@pwmillar.co.uk

P W Millar 148 Port Road East Barry South Glamorgan CF62 9PZ

Whilst every effort has been made to ensure the accuracy of the vehicle specification, some inaccuracies may occasionally occur. It is important that you do not rely solely on this information, but check with a member of the sales staff about any features which may affect your decision to buy the car.